

WISCONSIN MOTOR VEHICLE
CRASH REPORT

5QL2245WSR

Document Number Override		Primary Crash Document #	Agency Crash Number 24-109955	Investigating Officer/Deputy OFFICER H. GUREL	
Crash Date 03/15/2024		Crash Time 03:20 PM	Date Arrived 03/15/2024	Time Arrived 04:14 PM	
Date Notified 03/15/2024		Time Notified 03:37 PM	Total Units 02	Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input checked="" type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type PRIVATE PROPERTY/PARKING LOT		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p>	Reconstruction By
	Photos By
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

PER THE DRIVER OF UNIT 1'S STATEMENT, SHE WAS BACKING OUT OF A PARKING STALL AND MISJUDGED THE DISTANCE BETWEEN THE REAR OF HER CAR AND UNIT 2. UNIT 1 HIT THE DRIVER'S SIDE REAR CORNER OF UNIT 2 CAUSING SCRATCHES AND DAMAGE TO THE DRIVER'S SIDE REAR BUMPER CORNER OF UNIT 2. THE DRIVER OF UNIT 1 LEFT THE SCENE AND DID NOT LEAVE ANY INFORMATION. THE OWNER OF UNIT 2 WAS IN THE UPS STORE. A WITNESS SAW UNIT 1 DRIVE OFF AND PROVIDED THE LICENSE PLATE INFORMATION TO THE OWNER OF UNIT 2. WHEN I ARRIVED ON SCENE AT UNIT 1'S ADDRESS, I OBSERVED UNIT 1'S VEHICLE MATCHING THE DESCRIPTION AND PLATE NUMBER GIVEN BY THE WITNESS. THERE WAS A CRACK AND SCRATCHES ON THE PASSENGER SIDE CORNER OF THE REAR BUMPER THE REAR OF THE CAR WAS DUSTY EXCEPT FOR THE CORNER WHERE THE DAMAGE WAS WHICH APPEARED TO HAVE BEEN RECENTLY WIPED OFF. THE DRIVER OF UNIT 1 ADMITTED TO LEAVE THE SCENE AND CAUSING DAMAGE AND WAS CITED FOR HIT AND RUN TO AN UNATTENDED VEHICLE. PHOTOS ARE ATTACHED TO THIS CASE FILE.

5QL2245WSR
24-109955

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

Location

PARKING LOT UNIVERSITY AVE LOT 2858 (HOUSE/BUILDING 2858) IN THE VILLAGE OF SHOREWOOD HILLS IN DANE COUNTY	Latitude 43.074947582	Longitude -89.438248578
	X Coordinate 301499.96875	Y Coordinate 4772023
	Structure Type HOUSE/BUILDING	


Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT		First Harmful Event Location IN PARKING LANE OR ZONE	
Manner of Collision 04 - REAR TO REAR		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway NON TRAFFICWAY - PARKING LOT	
Crash Classification - Location PRIVATE PROPERTY		Crash Classification - Jurisdiction PRIVATE PROPERTY	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	

Unit Summary

UNIT	Unit Status HIT AND RUN		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit N/A	Total Lanes 0	
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT	Vehicle					
	01	License Plate Number [REDACTED]		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number [REDACTED]		Make VOLKSWAGEN	Year 2013	Model JETTA
	VEHICLE	Color BLU - BLUE		Body Style SW - STATIONWAGON		Bus Use
		Initial Contact Point 05 - RIGHT REAR CORNER		Vehicle Damage		
Extent Of Damage MINOR DAMAGE		05 - RIGHT REAR CORNER				



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OWNER	
	What Driver Was Doing LEAVING A PARKED POSITION		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions UNKNOWN			
01 01	Owner Name [REDACTED]		Owner Address [REDACTED]	
	Sequence Of Events			
01 02 03 04	Event MOTOR VEH IN TRANSPORT			
	Event			
	Event			
	Event			
UNIT	Policy Holder			
	Insurance Company AMERICAN-FAMILY-INS-CO		INDIVIDUAL [REDACTED]	
UNIT INDIVIDUAL	Individual			
	DRIVER [REDACTED]		Citations Issued 1	Sex FEMALE
	Address [REDACTED]		Date of Birth [REDACTED]	Race WHITE
	[REDACTED]		Driver License Number [REDACTED] STATE: WISCONSIN COUNTRY: UNITED STATES	
01 001	Safety Equipment		On Duty Crash	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT	
	[REDACTED]		RESTRAINT USE UNKNOWN	
	Helmet Use		Safety Equipment	
	Eye Protection		Helmet Compliance	
	[REDACTED]		Tint Compliance	
	Injury		Injury Severity NO APPARENT INJURY	
	[REDACTED]		Airbag NOT APPLICABLE	
Ejected NOT APPLICABLE		Ejection Path NOT EJECTED/NOT APPLICABLE		
Trapped/Extricated NOT APPLICABLE		Medical Transport NOT TRANSPORTED		
Hospital		EMS Agency Identifier		
[REDACTED]		EMS Run #		
[REDACTED]		Date of Death		
[REDACTED]		Time of Death		
Distracted By		Distracted By Source		
Distracted By Action				

WISCONSIN MOTOR VEHICLE
CRASH REPORT


UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
		Action				
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use		Suspected Drug Use	
	Alcohol Test Given		Alcohol Test Type		Alcohol Test Results	
	TEST NOT GIVEN					
	Drug Test Given		Drug Test Type		Drug Test Results	
	TEST NOT GIVEN					
	Drug Type					
Individual Condition		NOT OBSERVED				
Violations						
01	001	UTC Number	Issue To?	Statute Number	Description	
		BI350774	001	346.68	HIT AND RUN-UNATTENDED VEHICLE	

Unit Summary

UNIT	02	Unit Status		Vehicle Operating As Classification		Unit Type							
		LEGALLY PARKED		D CLASS		AUTOMOBILE							
		Vehicle Type				Operating As Endorsements							
		(SPORT) UTILITY VEHICLE											
		Total Occs		Train/Bus # Recorded		Total # Citations Issued		Total Trailers		Total HazMat Types			
		0				0		0		0			
		Insurance?		Direction Of Travel		<input type="checkbox"/> Pre Crash Tire Mark		Speed Limit		Total Lanes			
		YES		NOT ON ROADWAY				N/A		0			
		Most Harmful Event: Collision With				Special Function				Emergency Motor Vehicle Use			
		MOTOR VEH IN TRANSPORT				NO SPECIAL FUNCTION				NOT APPLICABLE			
Traffic Way				Traffic Control				Traffic Control Inoperative/Missing					
PARKING LOT OR PRIVATE PROPERTY				NO CONTROL				NO					
Surface Type				Road Curvature				Road Grade					
BLACKTOP (BITUMINOUS)				STRAIGHT				LEVEL					
Truck Bus or HazMat													
NO													

Vehicle

02	02	License Plate Number		Plate Type		St		Country of Issuance	
		[REDACTED]		AUT - AUTOMOBILE		WI		UNITED STATES	
		Vehicle Identification Number		Make		Year		Model	
		[REDACTED]		NISSAN		2018		PATHFINDER	
Color		Body Style				Bus Use			
RED - RED		UT - SPORT UTILITY VEHICLE							
Initial Contact Point									
07 - LEFT REAR CORNER									



5QL2245WSR
24-109955

WISCONSIN MOTOR VEHICLE CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

UNIT VEHICLE	Vehicle Damage	
	Extent Of Damage MINOR DAMAGE	07 - LEFT REAR CORNER
	Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR
	What Driver Was Doing LEGALLY PARKED	Vehicle Factors
UNIT VEHICLE	Driver Prior Action Other	NOT APPLICABLE
	Driver Actions NO CONTRIBUTING ACTION	
	Owner Name [REDACTED]	Owner Address [REDACTED]
UNIT VEHICLE	Sequence Of Events	
	01	Event PARKED MOTOR VEHICLE
	02	Event
	03	Event
	04	Event
UNIT	Policy Holder	
	Insurance Company PROGRESSIVE-UNIVERSAL-INSURANCE-COMP	INDIVIDUAL [REDACTED]