

5QL2HJN016
24-146342


WISCONSIN MOTOR VEHICLE CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

5QL2HJN016

Document Number Override		Primary Crash Document #	Agency Crash Number	Investigating Officer/Deputy OFFICER T. SCHWARZ	
Crash Date 04/09/2024		Crash Time 03:15 PM	Date Arrived 04/09/2024	Time Arrived 03:23 PM	
Date Notified 04/09/2024		Time Notified 03:18 PM	Total Units 01	Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input checked="" type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram 	Reconstruction By
	Photos By SHOREWOOD HILLS PD
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON THE ABOVE DATE AND TIME THE VEHICLE WAS TRAVELING WEST BOUND ON UNIVERSITY AVENUE AT UNIVERSITY BAY DRIVE. THE DRIVER STRUCK THE BASE OF THE TRAFFIC LIGHT SIGNAL AT UNIVERSITY BAY DRIVE. THE CONSTRUCTION WORKER THAT WITNESSED THE ACCIDENT ADVISED THE DRIVER APPEARED TO BE HAVING A SEIZURE. THE DRIVER WAS IN AND OUT OF CONSCIOUSNESS AND WAS TRANSPORTED TO UW HOSPITAL BY MFD. THE VEHICLE DID NO APPEAR TO STRIKE THE BASE TRAFFIC LIGHT AT A HIGH RATE OF SPEED.

5QL2HJN016
24-146342

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

Location

INTERSECTION ON 0 UBD UNIVERSITY AVE AT UNIVERSITY BAY DR (OTHER 0 UBD) IN THE VILLAGE OF SHOREWOOD HILLS IN DANE COUNTY	Latitude 43.073519333	Longitude -89.433792989
	X Coordinate 301858.125	Y Coordinate 4771854
	Structure Type OTHER	

Crash Scene

First Harmful Event TRAFFIC SIGN POST		First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION	Intersection Type FOUR-WAY INTERSECTION	
Work Zone Crash Location ACTIVITY AREA		Work Zone Crash Type WORK ON SHOULDER OR MEDIAN	
Workers Present YES		Law Enforcement Present NO	
Work Zone Speed Limit 30	Advisory/Regulatory Speed Limit ADVISORY	Normal Posted Speed Limit 35	

Unit Summary


UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE			Operating As Endorsements		
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? UNKNOWN	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 30	Total Lanes 3	
	Most Harmful Event: Collision With TRAFFIC SIGN POST		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY MEDIAN W/BARRIER		Traffic Control TRAFFIC SIGNAL		Traffic Control Inoperative/Missing NO	
	Surface Type CONCRETE		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					
01	Vehicle					
	License Plate Number [REDACTED]		Plate Type DLR - DEALER	St WI	Country of Issuance UNITED STATES	
Vehicle Identification Number [REDACTED]		Make VOLVO	Year 2024	Model TB SUV		

5QL2HJN016

24-146342

WISCONSIN MOTOR VEHICLE CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

UNIT VEHICLE	Color GRY - GRAY	Body Style UT - SPORT UTILITY VEHICLE	Bus Use
	Initial Contact Point 12 - FRONT	Vehicle Damage 12 - FRONT	
	Extent Of Damage MINOR DAMAGE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG	Vehicle Removed By
	What Driver Was Doing GOING STRAIGHT	Driver Prior Action Other	Vehicle Factors NOT APPLICABLE
	Driver Actions OTHER CONTRIBUTING ACTION	Owner Name [REDACTED]	Owner Address [REDACTED]
UNIT VEHICLE	Sequence Of Events		
	01	Event TRAFFIC SIGN POST	
	02	Event	
	03	Event	
UNIT VEHICLE	04	Event	
	Individual		
	DRIVER [REDACTED]	Citations Issued 0	Sex FEMALE
	Date of Birth [REDACTED]	Race	
Address [REDACTED]	Driver License Number STATE: WISCONSIN COUNTRY: UNITED STATES		
UNIT INDIVIDUAL	Safety Equipment		On Duty Crash
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	Safety Equipment SHOULDER & LAP BELT
	Helmet Use		Helmet Compliance
	Eye Protection		Tint Compliance
	Injury	Injury Severity POSSIBLE INJURY	Airbag NON DEPLOYED
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
Medical Transport EMS GROUND	EMS Agency Identifier 6000358	EMS Run #	
Hospital UW HEALTH-AMERICAN CENTER	Date of Death	Time of Death	

WISCONSIN MOTOR VEHICLE CRASH REPORT

UNIT	Distracted By		Distracted By Source UNKNOWN		
	Distracted By Action UNKNOWN				
	Non Motorist		Striking Unit #	Location	
	Prior Action				
	Action				
	Action Other				To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results
	Drug Type				
01	001	Individual Condition			
		PHYSICALLY IMPAIRED, ILL (SICK), FAINTED			
Property Owner					
PROP OWNER	01	[REDACTED]			[REDACTED]
		[REDACTED]			
Fixed Objects Struck					
01	Striking Unit 01		Struck Object TRAFFIC SIGN POST		Structure Number
					Damage Tag Number 1