

5QL314K13C
24-26411


WISCONSIN MOTOR VEHICLE
CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

5QL314K13C

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy OFFICER N. BARTELS	
Crash Date 01/19/2024		Crash Time 02:30 AM		Date Arrived 01/19/2024		Time Arrived 02:35 AM	
Date Notified 01/19/2024		Time Notified 02:33 AM		Total Units 01		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input checked="" type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

Diagram		Reconstruction By	
		Photos By OFC. BARTELS	
		Additional Information PHOTOS	
		<input checked="" type="checkbox"/> I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.	
<p>UNIT #1 WAS WESTBOUND ON UNIVERSITY AVE WHEN IT ATTEMPTED TO MAKE A LEFT HAND TURN ONTO N BLACKHAWK AVE. BECAUSE OF THE ICY/SNOWY ROAD CONDITIONS THE VEHICLE CONTINUED STRAIGHT AND HIT THE CURB TO THE CENTER MEDIAN AND BECAME STUCK ON A SNOW BANK. SCHMIDT'S TOWING ARRIVED AND GOT THE VEHICLE OFF THE SNOW BANK AND TOWED IT AWAY. UWPD TRANSPORTED THE DRIVER TO HER DESTINATION.</p>			

5QL314K13C
24-26411

WISCONSIN MOTOR VEHICLE CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

Location

ON UNIVERSITY AVE/ CTHMS WB 63 FT W OF N BLACKHAWK AVE IN THE VILLAGE OF SHOREWOOD HILLS IN DANE COUNTY	Latitude 43.075262831	Longitude -89.446903027
	X Coordinate 300796.40625	Y Coordinate 4772078.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event CURB	First Harmful Event Location ON ROADWAY	
Manner of Collision 00 - NO COLLISION W/VEHICLE IN TRANSPORT	Light Condition DARK/LIGHTED	
Road Surface Condition(s) SNOW, ICE	Roadway Factor(s) ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)	
Environment Factor(s) WEATHER CONDITIONS		
Weather Condition(s) SNOW		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control PARTIAL CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION-RELATED	Intersection Type FOUR-WAY INTERSECTION
Closure Type LANE CLOSURE	Reasons for Closure LAW ENFORCEMENT, TOW TRUCK	
Date Initial Lane/Rd Closed 01/19/2024	Time Initial Lane/Rd Closed 02:33 AM	
Date All Lanes Open 01/19/2024	Time All Lanes Open 03:29 AM	Date Scene Cleared 01/19/2024
		Time Scene Cleared

Unit Summary

01 UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE			Operating As Endorsements		
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 35	Total Lanes 3	
	Most Harmful Event: Collision With CURB		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, DIVIDED, UNPROTECTED (PAINTED > 4		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					
01	Vehicle					
	License Plate Number [REDACTED]	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES		
	Vehicle Identification Number [REDACTED]	Make FORD	Year 2019	Model ECOSPORT		

5QL314K13C
24-26411

WISCONSIN MOTOR VEHICLE
CRASH REPORT

SHOREWOOD HILLS POLICE DEPARTM
810 SHOREWOOD BOULEVARD
MADISON, WI 53705
(608) 267-1110

UNIT VEHICLE	Color BLK - BLACK		Body Style UT - SPORT UTILITY VEHICLE	Bus Use		
	Initial Contact Point 01 - RIGHT FRONT CORNER		Vehicle Damage 01 - RIGHT FRONT CORNER, 11 - LEFT FRONT CORNER, 12 - FRONT			
	Extent Of Damage FUNCTIONAL DAMAGE					
	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG				Vehicle Removed By	
	What Driver Was Doing LEFT TURN				Vehicle Factors	
Driver Prior Action Other		NOT APPLICABLE				
UNIT VEHICLE	Driver Actions SPEED TOO FAST/COND					
	Owner Name [REDACTED]		Owner Address [REDACTED]			
UNIT 01	Sequence Of Events					
	01	Event CURB				
	02	Event				
	03	Event				
	04	Event				
UNIT	Policy Holder					
	Insurance Company GEICO-GENERAL-INS-CO		Individual [REDACTED]			
UNIT INDIVIDUAL	Individual					
	[REDACTED]		Citations Issued 0	Sex FEMALE		
	[REDACTED]		Date of Birth 12/05/1997	Race HISPANIC		
	Address [REDACTED]		Driver License Number [REDACTED] STATE: WISCONSIN COUNTRY: UNITED STATES			
UNIT 01	Safety Equipment		On Duty Crash			
	Safety Equipment		SHOULDER & LAP BELT			
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	Helmet Compliance			
	Helmet Use		Tint Compliance			
	Eye Protection		Airbag NON DEPLOYED			
	Injury		Injury Severity NO APPARENT INJURY	Trapped/Extricated NOT TRAPPED		
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE			
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #			

